

FIRMWARE: 1.6.12.42

GENERAL UPDATES

- Changed the default speaker preset setting to be 80 Hz for the HPF (LA models) or LPF (S models).
- Fixed a bug that was preventing the DSP from automatically rebooting when the main line voltage would drop for more than 300ms.
- Fixed a bug related to the mute ramp time.
- Fixed a bug related to the resolution of octave values when connecting to JBL Performance.
- Fixed a bug where the IP address information was not reported back to JBL Performance correctly after a System Reset.
- Fixed a bug where the IP gateway was improperly reported for APIPA addresses.

SRX918S

- The SRX918S gain setting (sensitivity) was adjusted to be 6dB less than SRX928 to allow 2x SRX918S to be the same output as 1x SRX928S.
- Fixed issue where EQ status was not reported correctly on the LCD.

SRX928S

- Gain settings were adjusted to better match VTX B Series gain structures and to be the same level as 2x SRX918S.
- Fixed issue where EQ Status was not reported correctly on the LCD.

FIRMWARE: 1.6.8.29

GENERAL NOTES

Initial public release

SRX900 firmware is universal and the same file is used for the SRX910LA, SRX906LA, SRX918S and SRX928S models.