

REVISION HISTORY

Version 1.0:

- Initial VTX A6 / B15 EASE GLL release.

Version 1.1:

- Addressed a problem regarding a splay angle error between A6 and B15 cabinets. The angle was incorrectly set to 0 degrees, and it's now set to 6 degrees.
- Updated the drawings of the A6 Mini Frame to show the correct parts.